IREDELL COUNTY HEALTH DEPARTMENT III B 462750 7441

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER CONTRACTOR Robert Sink DATE Feb 11, 87 PERMIT NO. 62

PHONE Business Home

LOCATION 1100 TR 1115 - TR 1215 (Crushstone) left at forks 1/4 mile TR Rhinehill Dr. at end

SUBDIVISION NAME L.N. LOT NO. 426 SECTION OR BLOCK NO. 8 S. R. No.

Sale Easement on Creek left Lot 2 on 1215

House Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Washing Machine Yes (✓) No ( )

Site Suitability Yes (✓) No ( )

Lot Area 1A

Character & Porosity of Soil clay Easement Area

Percolation Rate ~, 4

Topography 2-4%

Depth to Water Table 4'+

Rock or other impervious formations none obs.

Basement with Plumbing ____ Basement without Plumbing ____ No Basement ✓

1000 gal pump tank

Size of Tank 1000 Gals.


Nitrification Field:

No. of Lines 4

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )



Plot of System

Installed by J.J. Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY JCM

COMMENTS:

CERTIFICATE OF COMPLETION BY D.R. Hinson, RS. DATE Feb 11, 87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold