ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: PCT APPLICATION DATE _____

ADDRESS: _____ DATE EVALUATED: 4-16-03

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: [illegible] 30A S to 23SE PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	30A	0-4	[illegible]	[illegible]	[illegible]				.3
		4-31	MFSBK	RC	SI-CL-SP SOL				
		31-46	[illegible]	[illegible]	[illegible]				
2	[illegible]	0-[illegible]	[illegible]	[illegible]	[illegible]				.35
		[illegible]	MFSBK	[illegible]	[illegible]				
		[illegible]	[illegible]	[illegible]	[illegible]				
3	29A	0-6	GR	[illegible]	[illegible]				.3
		6-24	MFSBK	RC	[illegible]				
		24-48	MFSBK (RC)	[illegible]	[illegible]				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

COMMENTS: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CKL APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-15-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 36 COS Hunsucker Cy PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1941 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	SL Rbk sol fr						PS = .3
		6-30	mod sbk RC	fr sp					
		30-55	wk-mod sbk ygrel/l	fr-ss sp					
2		0-16	gr-sbk vfsl sol	fr					PS = .25
		16-29	SAB vfsl/el/l	fr ss sp	few yhbm mott				
		29-61	wk-mod sbk rel/l	fr-fr ss sp					
			few-com yhbm mott						
3	Now SFE 29A	0-6	sol						PS = .3
		6-40	mod sbk vfsl/el	fr ss sp					
		40-57	wk sbk ygrel/l	fr ss sp					
4		0-12	compacted sl/c						PS = .3
		12-36	mod sbk hbrn cl/sic	fr ss sp			restrictive	36"	.46
		36-55	wk sbk ygrel	fr ss sp					
			few-com rm cl sp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


38-4
38-5
38-2
38-1
38-3
17-6
17-3
37
S13° 58' 15" E 257.38'
S89° 41' 12" W
130.74'
135.00'
N73° 41' 03" E
63.95'
S89° 41' 12" W
135.00'
S00° 18' 48" E
130.00'
N89° 41' 12" E
208.30'
S73° 16' 57" E
220.42'
S73° 16' 57" E
270.24'
S73° 16' 57" E
216.58'
N74° 00' 25" W
168.74'
107.25'
148.88'