9627822499

11825

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Richard Miller DATE 2/25/91 PERMIT NO. 2L-4-A-57

PHONE: Business _____ Home 919-998-7770

LOCATION Beaten Path, Brawley School TR BLUME, TL Beaten Path, TL at forks, approx 1.5 miles on ® at mailbox #260, on right side of road S. R. No. 1443

SUBDIVISION NAME Crescent Properties LOT NO. 57 SECTION OR BLOCK NO. 9

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 20,000

Character & Porosity of Soil clay

Percolation Rate 4


Topography 2-3%

Depth to Water Table >48"

Rock or other impervious formations None found

LAKE LAKE LAKE REPAIR 100' X 9' BED

_____ Basement with Plumbing 100' Basement without Plumbing ✓ No Basement



Plot of System BEATEN PATH RD.

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 5

Sq. Ft. 1462 Linear Ft. _____

Depth of Stone in Lines 13"

Water Supply: Individual (✓)

Public ( )

562.5 FT²
+900 FT² NEW
1462

Installed by Donald Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 2/25/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold