11825

REPAIR

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Richard Miller DATE 2/4/91 PERMIT NO. 2L-4-A-57

PHONE: Business _____ Home 919-998-7770

LOCATION 260 Beaten Path Rd, 1 mile on (R) to #260

S. R. No. 1443

SUBDIVISION NAME Crescent Properties LOT NO. 57 SECTION OR BLOCK NO. 9


House (✓) Mobile Home ( ) Business ( ) Other 760 CONTOUR

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	4
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-3%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'
			Rock or other impervious formations	None found

Lot Area _____

_____ Basement with Plumbing 100' x 9' Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank EXISTING 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

+ 225 FT² EXISTING
1125 FT²

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Wesley Sparks RS.

BRADLEY SCHOOL

COMMENTS:

Use Bull Run Valve before Distribution Boxes as shown in diagram.
Keep additional bed 50' from 760 contour lines (wood stakes & flags)
50' from drilled well

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold