11825

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR RICHARD MILLER DATE 1/17/91 PERMIT NO. 2L-4-A-57

PHONE: Business _____ Home 919-998-7770 / 664-6986

LOCATION 260 BEATEN PATH RD. / SR1443 - 1 mile on R, # 260

S. R. No. 1443

SUBDIVISION NAME Crescent Prop. LOT NO. 57 SECTION OR BLOCK NO. 9


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	( )	No	(✓)	Character & Porosity of Soil EXISTING SYSTEM
Auto. Dishwasher	Yes	(✓)	No	( )	Percolation Rate
Auto. Wash. Machine	Yes	(✓)	No	( )	Topography
Site Suitable	Yes	(✓)	No	( )	Depth to Water Table
					Rock or other impervious formations

Lot Area Existing

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank EXISTING 1000 Gals.

Nitrification Field:

No. of Lines _____

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual (✓)

Public ( )

EXISTING 225 FT² SYSTEM

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Old Completion Certificate found under P.D. Thompson. No signs of malfunction on the date of this inspection. There is room for repair system and staying 50 feet away from the lake area.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: Wesley Sparks R.S. / D.R. Hinson, EHC DATE 1/17/91

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold