DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bridgewater APPLICATION DATE: ___
ADDRESS: ___
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 480 gpd DATE EVALUATED: 7-30-03
LOCATION OF SITE: Lot 13 Greenbay PROPERTY SIZE: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-47	gr-wkSBK light brn	LS frss-nsnp					.5
2	16%	0-32	gr light brn SL	LS frss-nsnp					.4
		32-50	wkfSBK yr-light brn scl	frsssp ssp					
3		0-21	gr-wkSBK light brn SL	frsssp					.3-.4
		21-50	(B-C) wkfSBK yr scl	frsssp	common in lsp				
4		0-14	gr brn SL	frsssp					
		14-29	wkfSBK yr scl	frsssp	(upslope) (downslope - 24" fgsc bedrock) Restrictive				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	CONV. CONV.	CONV. CONV.
Site LTAR	.4	.4

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: DLH
OTHER(S) PRESENT: Paul Pennington

COMMENTS: ___