DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-13-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 16 Pennacle 4 COS PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

(5) 0-6 brn sl sbk sp
6-20 sbk sc sp
20-53 mottled sc sp
53-60 R sl sp

PS .3

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | ridge pad | 0-13 | massive sl | fr sssp | | | | | PS .25 |
| | | 13-29 | mfsbk scl/cl | fr sssp | | | | | |
| | | 29-61 | mfsbk RC | vfi in place sp | | | | | |
| | | | few y brn mottles | | | | | | |
| 2 | | 0-12 | gr sl | fr | | | | | PS .25-.3 |
| | | 12-32 | sbk rc/cl | fi sp | | | | | |
| | | 32-60 | WK sbk rel | fi sssp | | | | | |
| | | | lawind sap | | | | | | |
| 3 | | 0-15 | Brn SCL | Gr Fr | | | | | PS .25-.3 |
| | | 15-36 | Rd CL mSBK | Fi S, P, SE | | | | | |
| | | 36-60 | Rd CL WSBK | SS, SP, Fi | | | | | |
| 4 | | 0-9 | gr brn sl | fr | | | | | PS .3 |
| | | 9-37 | mfsbk rc/cl | fi sp | | | | | |
| | | 37-56 | mk sbk yrd | fi sssp | | | | | |
| | | | common red sap | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____