DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: CRL OWNER: __ AGENT: __ PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 9-15-95
PROPOSED FACILITY: ____
PROPERTY SIZE: ____
LOCATION OF SITE: Lot 72, Pinnacle Shores 1B
WATER SUPPLY: On-Site Well ____ Comm. Well ____ Public ____ Other ____ EVAL. METHOD: Auger Boring ____ Pit ____ Cut ____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-6	gr Loa sL	fr					.3
		6-19	MSAB RC	fr SSP					
		19-36	MSAB RCL	fr SSP common mica					
		36-46	WKSAB RSL	fr SSP					
2		0-7	gr- SL	fr					.3
		7-40	M-WKSAB- RCL	fr SSP					
		40-46+	WKSAB RCL	fr					
3									
4									
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: ____

EVALUATED BY: ____ OTHER(S) PRESENT: ____

COMMENTS: ____

74
73
71
70
69
V1
308.31'
190' BSL
110' BSL
270.63'
60'
BASEMENT
CRAWL
18.75'
DRIVE
60' BSL
192.13'
70.00'
125' BSL
312.45'
247.54'
100.00'
55' BSL
35' BSL
85' BSL
L=25.29'
L=75.06'
L=15.35'
L=43.67'
L=63.11'
L=170.95'
40.07'
36.58'
20685
20684
20688
20687
20678
20675
20674
20689
20690
20680
LPPBPS
Initial
Inspection