DEPARTMENT OF ENVIRONMENT, HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH


PROPERTY I.D.#: _____
PROPERTY RECORDED: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## FOR
## ON-SITE WASTEWATER SYSTEM

APPLICANT: CRI OWNER: __ AGENT: __ PHONE: _____ DATE EVALUATED: _____
ADDRESS: _____ APPLICATION DATE: _____
PROPOSED FACILITY: _____
PROPERTY SIZE: 53 A Spruce Pine
LOCATION OF SITE: Famous Gittens EVAL. METHOD: Auger Boring ___ Pit ___ Cut ___
WATER SUPPLY: On-Site Well ___ Comm. Well ___ Public ___ Other _____

| PROFILE # | .1940 LANDSCP POS. (%) | HORIZON DEPTH (IN.) | .1941 STRUCTURE/TEXTURE | .1941 MINERALOGY/ CONSISTENCE | .1942 WETNESS COND. | .1944 RESTRICT HORIZONS | .1948 CLASS OF HORIZ | 1943/ 1956 SAPRLT CLASS. | HORIZON LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-10 | gr - [illegible] scl | 1:1 [illegible] | | | | | |
| | | 10-17 | gr - Brn scl | 1:1 fr | | | | | |
| | | 17-48 | msbk scl | 1:1 fr-sfi | | | | | |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |

AVAILABLE SPACE (.1945) _____ SITE CLASSIFICATION (.1948): _____ SITE LONG-TERM ACCEPTANCE RATE: _____
EVALUATED BY: _____ OTHER(S) PRESENT: _____
COMMENTS: _____


64
35,016 Sq. Ft.
0.804 Ac.+/-
34,196 Sq. Ft.
0.785 Ac.+/-
62
61
42,495 Sq. Ft.
0.976 Ac.+/-
60
42,655 Sq. Ft.
0.979 Ac.+/-
CONSTRUCTION PHASE LINE
41,850 Sq. Ft.
0.961 Ac.+/-
58
400.84
NEW-LOT
356.32
51.14
107.55
248.78
153.49
51A
120.00
216.18
47A
NEW-LOT
96.58
130.00
52A
133.89
126.74
53A
45A
151.00
140.00
106.58
82
39,512 Sq. Ft.
0.907 Ac.+/-
83
84
34,926 Sq. Ft.
0.802 Ac.+/-
85
27,922 Sq. Ft.
0.641 Ac.+/-
86
87
34,549 Sq. Ft.
33,549 Sq. Ft.
0.770 Ac.+/-
34
33
31,129 Sq.
0.715 Ac.
21