DEPARTMENT OF ENVIRONMENT, HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___
PROPERTY I.D.#: ___
PROPERTY RECORDED: ___
COUNTY: ___

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: CRI OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 6/22/95
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: lot 47 Pinnacle Shores
WATER SUPPLY: On-Site Well ___ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-20	ms sl - c						.3
		20-32	wpbk - cl						
		32-48	wk sbk fri						
2		0-10	gr/wsag sc l	fr ss/sp					.3
		10-45	m/s sad hvy cl	fi ss/sp					
3		0-7	gr, cl	fr					.3
		7-23	wsbk c	fi ss/sp					
		23-41	mpbk cl	fi ss/sp					
4									
5									


AVAILABLE SPACE (.1945): ___ SITE CLASSIFICATION (.1948): ___ SITE LONG-TERM ACCEPTANCE RATE: ___

EVALUATED BY: ___ OTHER(S) PRESENT: ___

COMMENTS: Marked Soil ok - Repair area ok - Trench like due to old trench and spoil pile.

Off Site system — other septic systems in area

1 of 1 4/5


64
35,016 Sq. Ft.
0.804 Ac.+/-
34,196 Sq. Ft.
0.785 Ac.+/-
62
61
42,495 Sq. Ft.
0.976 Ac.+/-
60
42,655 Sq. Ft.
0.979 Ac.+/-
CONSTRUCTION PHASE LINE
41,850 Sq. Ft.
0.961 Ac.+/-
58
400.84
NEW-LOT
356.32
51.14
107.55
248.78
153.49
51A
120.00
45A
47A
216.18
NEW-LOT
96.58
130.00
52A
133.89
47A
45A
151.00
140.00
106.58
126.74
53A
LPPBBS Repair
34
33
31,129 Sq.
0.715 Ac.
82
39,512 Sq. Ft.
0.907 Ac.+/-
83
84
34,926 Sq. Ft.
0.802 Ac.+/-
85
27,922 Sq. Ft.
0.641 Ac.+/-
86
87
33,549 Sq. Ft.
0.770 Ac.+/-
28,00
0.643
21
34,549 Sq. Ft.
22,929 Sq. Ft.
0.526 Ac.+/-
SE

DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: CRT OWNER: AGENT: PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: ____
PROPOSED FACILITY: ____
PROPERTY SIZE: 2+ ____
LOCATION OF SITE: 479A East Entre Pinnacle ____
WATER SUPPLY: On-Site Well ____ Comm/ Well ___ Public ___ Other ____ EVAL. METHOD: Auger Boring ___ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-30	vc sdy loam	fg					.34
		30-48	wk sb stl	fr					
2									
3									
4									
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: ____

EVALUATED BY: ____ OTHER(S) PRESENT: ____

COMMENTS: Some pinnacles over much of site
maybe Kvotchina ver #7