IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Randy Link

DATE REQUESTED: 6-23-80

ADDRESS: Iredell

PLAT NO.: LN Sec 11 Lot 296

COUNTY: Iredell

LOT SIZE: ~1 Acre

LOCATION OF SITE: 150W TR 1438 2 Yards on R

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 15-20%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	(S) PS U clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	(S) Sub- PS Angular U Blocky	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 48+ U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) PS None U observed	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) PS No U mottles	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	(S) PS 80 U mpi	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	PS			
SOIL SERIES	? Cecil weathered	Parent material		

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: Follow contours of hill with lines - keep at least 1-1/2 COVER of fill lower side of trench

Described By: Fred Clemmer

Title: S-I

Date: 6-23-80

DHS Form 2601 (2/77)
Sanitation