4628878579

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Randolph C. Eason DATE 4-29-77 PERMIT NO. 85

PHONE: Business Perth Home 918-282-8295

LOCATION 163 to Turn 1st on 3rd turn and TR at end on right

Fern Hill S. R. No.

SUBDIVISION NAME — LOT NO. — SECTION OR BLOCK NO.

Site Address: 162 Fern Haven Ln - Mrsvl.


House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Sandy Clay loam	Average (Good)
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	1	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2% Slope	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	12"	
			Rock or other impervious formations	None	

Lot Area 1.27 ac

Lake



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 625 Linear Ft. 250'

Depth of Stone in Lines 10"

Water Supply: Individual (✓)

Public ( ) well next door

Installed by Don Lentz

IMPROVEMENTS PERMIT BY J. C. Mark

COMMENTS:

CERTIFICATE OF COMPLETION BY John Sheridan DATE 4-29-77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Randolph G. Ensign DATE 9-22-76 PERMIT NO. 328

PHONE: Business [illegible] Home 919-293-8203


LOCATION Rt 1303 North TL on 1300 before end
Turn right at entron right S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other Adding to existing cabin

No. Bedrooms 3 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area [illegible]

Character & Porosity of Soil Sandy clay loam (Porosity) Fair
Percolation Rate Soil borings 5' Good
Topography 2% slope
Depth to Water Table 10'+
Rock or other impervious formations none



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )
well next door

Installed by

ditch
5'x125'
2 lines

IMPROVEMENTS PERMIT BY D. C. Moore

COMMENTS:

CERTIFICATE OF COMPLETION BY DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold