DENR/DEH

ON-SITE WASTEWATER SECTION

Sheet ___ *of* ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Chad Goodin — APPLICATION DATE _____
ADDRESS: _____ — DATE EVALUATED: _____
PROPOSED FACILITY: 4 bedroom — PROPOSED DESIGN FLOW (.1949): 480 gpd — PROPERTY SIZE: _____
LOCATION OF SITE: Morrison Pt. #19 — PROPERTY RECORDED: _____
WATER SUPPLY: • X Private • Public • X Well • Spring • Other _____
EVALUATION METHOD: • Auger Boring • X Pit • Cut — TYPE OF WASTEWATER: • X Sewage • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	3-5%	0-17	Rc sbk	Fr sss p	—	28"	Few Sap Inc	—	PS 0.3
		17-28	Rcl wsbk	Fr sss p					
		28-59	sl sap m	Fr sss p			PS		
		*	Not In System Area *						
2	3-5%	0-22	Rc sbk	Fr sss p	—	55"	Few Sap Inc	—	PS 0.3
		22-53	Rcl wsbk	Fr sss p					
3	3-5%	0-23	Rbscl wsbk	Fr sss p	—	52"	—	—	PS 0.3
		23-52	R cws bk	F-Fr sss p					
4	3-5%	0-31	R Bscl wsbk	Fr sss p	[illegible]	52"	—	—	PS 0.3
		31-52	R cwsbk	F-Fr sss p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	540 ft²	NA
System Type(s)	PPBPS	
Site LTAR	0.3	

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: GM + MA
OTHER(S) PRESENT: _____

COMMENTS: _____