Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1
Property ID: 4628-96-7301
Lot #: 2
File #: Repair
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Fredrick Fischer
Applicant:
Address: 111 Point of View Ln. Mooresville, NC 28117
Date Evaluated: 5/4/2010
Proposed Facility: SFR Design Flow (.1949) 480 GPD
Property Size:
Location of Site: Point of View Lot 2
Property Recorded: Yes
Water Supply: [ ] Public [x] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [x] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB	LINEAR	0-17	R,SCL,M,SBK	SS,SP,SEXP,FR	NA				
#1	~5%	17-21	R,SCL,W,SBK	SS,SP,SEXP,VFR	NA				
		21-36	R,SC,M,SBK	SS,SP,SEXP,FR	NA				
		36-56	R,SCL,W,SBK	SS,SP,SEXP,VFR	NA				
		56+	R,LSAP	NS,NP,VFR	NA	56"	S	NA	.35

Description	Initial System	Repair System
Available Space (.1945)		PS
System Type(s)		Gravity Panel
Site LTAR		.35

Other Factors (.1946):
Soil Evaluation By: Ben Aldridge
Others Present: None
Site Classification (.1948):
Site Evaluation By: Ben Aldridge
Others Present: None