ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12-8-99

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: 1037 638 Tarkan Bay PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	Sl rbk cl	fr					IS .3
		6-28	[illegible]	[illegible]					
		28-40	BC mott 2yr cl	fr sst common mica sp					
39		40-47	LSCkp						
2		0-5	sl brn sl/scl fr						.25 .3sp
		5-25	SBK c	fr sso					
39		25-40	wk csbk rd	fri sl sp fr sso sp					
		40-53	LSAp	fr sso sp					
38 1		0-12	sl brn scl	fr sso sp					IS .3
		12-34	wk sbk RY c	fr sso fri sl sp					
		34-49	(BC) wk csbk RY, Y brn scl	fr sso sp					
38 2		0-5	sl brn sl fr						IS .3
		5-27	SBK yr c	fr sp					
		27-52	wk csbk yr scl	fr sso common mica sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Usable Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____