DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 121576
COUNTY: 4629-58-6794

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICANT
OWNER: Britton Custom Homes/Lawrence APPLICATION DATE: ___
ADDRESS: PO Box 2218 Davidson NC 28036 DATE EVALUATED: 6-26-24
PROPOSED FACILITY: House 3BR PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 0.08±
LOCATION OF SITE: Wildlife Blvd Lot 37 PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☒ Other Community
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	4% L 2	0-24	c mod sbk	fi sp so/po					PS .3
		24-48	cl/sicl wk sbk	fr ss sp so/po					
3 S2	4% L	0-24	c mod sbk	fi sp so/po		36" 50% with c LP	removal		PS .3
		24-36	cl/sicl wk sbk	fr ss sp so/po					
		36-48	saprolite wk st	fr ss sp so/po					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	YES	YES
System Type(s)	LP 50% wall	LP 50% wall
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: L. Lodge
OTHER(S) PRESENT: ___

COMMENTS: ___