09504

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR THORNTON BROOKS DATE 3-13-89 PERMIT NO. 17D.

PHONE: Business _____ Home _____

LOCATION Morrison Farm Rd. off State Park Rd. - T.R. on Bacillus Point Rd. - then T.R. on 1st dirt drive go to the end. S. R. No. _____

SUBDIVISION NAME SECTION 17 LOT NO. 85 SECTION OR BLOCK NO. _____

KEVEN DRIVE.

House ( ) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No ( )
Auto. Dishwasher Yes ( ) No ( )
Auto. Wash. Machine Yes ( ) No ( )
Site Suitable Yes ( ) No ( )

Character & Porosity of Soil Prop. Suitable.
Percolation Rate 4 gal/sq. ft.
Topography 2-10% slope
Depth to Water Table 10+
Rock or other impervious formations none observed.

Lot Area Ample.

___ Basement with Plumbing ___ Basement without Plumbing ___ No Basement




Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 900 Lineal Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public ( )

Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 3-13-89.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold