On-Site Wastewater Inspection Report (Page 1 of 2)

☑ **Pre-Inspection Contract, signed by Client is attached to Inspection**

Property Address 109 Cromdale Rd
Street Address

Troutman City | NC State | 28166 Zip

Client Name Jill See / Keller Williams Realty
Leslie & Rosalynn Miller (Buyers)

Date of Inspection 29-Jul-2013

Current Owner of Record

_____ Advertised number of bedrooms as stated in attached sworn statement by owner or owner's representative

360 Gallons per day for designed system size or number of bedrooms as stated in available local health department information

☑ Inspection shall include any part of the system located more than 5 feet from the primary structure that is part of the operations permit

☑ Copy of Operations permit from Iredell County Environmental Health attached

☐ Operations permit not available

☐ System requires a certified subsurface water pollution control system operator pursuant to G.S. 90A-44
Current Operator's Name _____
Most recent performance, operation and maintenance reports are

Type of water supply: Well

Location of Septic Tank and septic tank details:

10 ft from house or structure
100+ ft from well if applicable
_____ ft from water line if applicable
_____ ft from property line if said property lines are known or marked
-15" distance from finished grade to top of tank or access riser

No	Access riser(s)	Description:
Yes	Tank lids intact	
Yes	Tank has baffle wall:	Description:
	Inflow to tank is noted as: **Sufficient**	
Yes	Water level in tank is relative to tank outlet	
No	Outlet T is present	Description: Concrete sanitary T had crumbled
No	Outlet has filter	Description:
Yes	Effluent leaves the outlet	
No	Roots present in tank	Description:
No	Evidence of tank leakage	Description:
No	Evidence of non-permitted connections, such as downspouts or sump pumps * (Any found will be in general comments)	
Yes	Connection present from house to tank	
Yes	Connection present from tank to next component	
0%*	Percentage of solids in tank	Description: Very thick amount of solids, but tank was pumped during the visit

Unable to locate tank. System inspection cannot be completed until tank is located

Date tank was last pumped: 29 July 2013

Client requesting this inspection has been advised that for a complete inspection to be performed the tank needs to be pumped. Client has declined to have the tank pumped at inspection and hereby acknowledges the have so declined.

Client Signature _____ Date _____