No Copy

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Charlie Gillon DATE 1/4/78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Farm on Perth Rd at Troutman, T.R. on 1321. T.L. 1st Rd Past 1447. T.R. House on L. beyond big Power Line S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (+) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit	Yes ( )	No (+)
Auto. Dishwasher	Yes (+)	No ( )
Auto. Wash. Machine	Yes (+)	No ( )
Site Suitable	Yes (+)	No ( )

Lot Area 20 000 Sq ft.


Character & Porosity of Soil _____

Percolation Rate _____

Topography Existing

Depth to Water Table _____

Rock or other impervious formations _____



Plot of System

Existing

Size of Tank _____ Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines _____

Water Supply: Individual (+)

Public ( )

Installed by F. J. Erwin

8/29/75

Addition To Existing House

IMPROVEMENTS PERMIT BY _____

COMMENTS: Old Tank replaced by F. J. Erwin. Did not Notify Health Dept. old Tank to be Pumped out and collapsed. This existing system appears to be working O.K. at this Time

CERTIFICATE OF COMPLETION BY E. A. Stevenson DATE 1/4/78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold