N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICATION DATE _____

DDRESS: _____

ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 480gpd DATE EVALUATED: 3-11-04

OCATION OF SITE: Lot 1330 Lot is The Ft PROPERTY SIZE: _____

'ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____

VALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut

YPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	wk sbk br cl	fr sss p					
		6-39	mod/wk sbk RC	fr SO SSP	+ bottom seeping out at backslope				.3
		39-52	mod/wk yel cl	fr sss p	Hard pan mid slope				
2	#21 TC 6% + SL	0-9	gr bk L	vfr sss p					
		9-38	mod/wk RC	fr sss p					.3
		38-50	mod/wk RCL	fr sss p	mottles in lower				
3		0-3	gr/wk sbk brn cl						
		3-16	mod/wk sbk RC	fr sss p					.3
		16-40	wk sbk yel cl	fr sss p					
4		0-7	gr bk L	fr sss p					
		7-23	mod/wk sbk RC	fr sss p					.3
		23-51	mod/wk yel cl	fr sss p	Hard pan mid slope				
					Perched water on wet side of pit				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	LPPBPS	LPPBPS
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: DH

OTHER(S) PRESENT: Paul Pennington

COMMENTS: _____