DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRL APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-23-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 71 The Pointe PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed Now Lot 70

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	gr sl br sl	fr					PS .3
		9-31	wk sb RC	fr ss					
		31-39	wk sb RCL	fr ss sp sbk					
			mod sbp						
2	#15 TCA EXP	0-24	RC						PS .3
		24-45	mod sb yRCL	fr ss sp					
			common brp						
3		0-6	gr sb br sl	fr ss sp					PS .3
		6-25	SAB RC	fr ss sp SND					
		25-48	wk SAB yR CL	fr ss sp sbk					
			common mod sbp						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


SEE
SHEET 4 OF 00
176'
S37°12'14"E
63.75'
88'
122'
280'
262'
146'
204'
L265
L275
DRIVE
20' USE
#3 Near
Septic 80'
Old Fence LINE
#75
CRAWL
80'
not enough slope
Basement
ST
76
71