SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Cutts APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Lot 39 The Pointe PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	V Wet	0-3	SL						S 3
		3-32	SiCL blocky	Gravelly					
		32-80	w/ 50% Rock	Fragments					
			Limited	Depth					
2	#108 TCJ	0-4	Fine SL						S 3
		4-32	w/ 40% Rock Fragments						
		32-48	SL w/ 60% Rock Fragments						
			Common Mottling						
3									
4									


DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____


RECREATION – 3.91 ACRES
40'
149'
129'
122'
123'
97'
155'
MATCH LINE
120
32
115
230'
226'
220'
228'
70² CRAWL
41
40
39
38
70² CRAWL
70² CRAWL
DRIVE
DRIVE
DRIVE
35' SETBACK
VINEYARD DRIVE
137'
126'
104'
S37°12'14"E
300.23'
24'
50'
152'
127'
130'
201'
35' SETBACK
PC = 26+22.81
PT = 27+27.57
Contour
Prompt top?
UPtrail
w/Life Expan