DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ORT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-20-96
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 37 The Pointe PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Hold until further review. Can move forward, put initial septic w/ 5 sep

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-5	gr lam sa L/sk fr		~36"?				PS .25 ~36"
		5-11	sbk RC	fr ≤ P SSO					
		11-40	msbk/ab yel	fr p/ss SS/P					
			few fm. chrom mottles sometimes						
			water adding in pit from ~36"						
2		0-7	gr lam sl/cl						PS .3
		7-26	msbk RC	fr ss/p					
		26-43	wkmsbk yel	fr ss/p SS/P					
3	TCS #110	0-5	gr lam sl	fr					PS .25
		5-27	msbk/ab RC	fr/firm when moist ss/p	Manufactured fr ss/p				
		27-49	msbk/ab yel RC	fr ss/p					
			common fm grey mottles						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____