DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: CKT _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-16-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 100 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE | 1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1956 SAPRO CLASS | 1944 RESTR. HORIZ. | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-6 | | | | | | | PS 0.5-3 |
| | | 6-21 | | | | | | | |
| | | 21-45 | | | | | | | |
| 2 | | 0-6 | | | | | | | PS 0.5 |
| | | 6-28 | | | | | | | |
| | | 28-45 | | | | | | | |
| 3 | | 0-8 | | | | | | | PS 0.5 |
| | | 8-28 | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

226'
35' SETBACK
128'
ACCESS
64'
24'
50'
PT = 30+70.19
R=50'
R=36'
20' PSDE
71'
89'
L148
108'
DRIVE
SETBACK
35'
change to 3BR
60'x80'
House this
Commerce
Install
3@90'270
panel
11+00
PT = 11+10.09
Delta=26.25.09"
L=110.09'
R=238.75'
Tan=56.04'
24'
50'
253'
S57°11'28"E
192.62'
174'
CRAWL
BASEMENT
20' PSDE
DRIVE
256'
125'
128'
S32°48'32"W
110.00'
18'
269'
119.73'
93'
116'
150'