DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Ott APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-10-93
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 117 The Pointe (Old 73) PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

Do another pit Now Lot 113

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	new L nl%	06	gr sbk benscl						PS -3
		6-55	sbk	R c/ CL					
2	new L nl-15% adventitious	0-36	Sl brn c/ CL sbk str						
			many manganese coatings						
			14" water in pit bottom						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

STREET
25' SETBACK
74'
28'
24'
50'
55' SETBACK
136'
141'
50'
108'
DRIVE
25' SETBACK
223'
293'
DRIVE
35' SETBACK
130'
309'
50' SETBACK
155'
144'
L50
176'
20' PSDE
L11
CRAWL
BASEMENT
80'
L10
CRAWL
BASEMENT
80'
S89°07'08"W
88.26'
140'
R=36'59 R=50'
R=225.00'
Delta=55°51'43"
Tan=119.29'
=219.37'
PT = 12+19.37
PT = 13+07.62
PC = 18+22
10+00
11+00
12+00
13+00
14+00