ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-10-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Need another ... Now Lot 11D

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	2 -8%	0-20	mSaBRC	fr ssp sbw					PS .3
		20-46	fr sl gr fsl	fr ss ps sbw					
			fsl w/ sl gr						
2	6-1-98	0-29	slb c/ct	fr sp ss sbp					PS .3
		29-47	(B1C) msb c/ct	fr sp ss					
			few. common ind	sp					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


155'
144'
135'
50'
309'
232'
262'
273'
20' PSDE
DRIVE
DRIVE
SETBACK
140'
35' SETBACK
42' SETBACK
SETBACK
143'
130'
71'
65'
46'
43'
18'
R=36'
R=50'
L=479.13'
MOOR
RE
11+00
12+00
13+00
1+00
1+04.81
Contour
100'
BASEMENT
CRAWL
808
809
811
811
813