DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CPI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-18-16
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Septic Matters Cove Lots 112 & 111 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Lots 111 & 112
Now 107A & 108A

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	108A 6-8%	0-6	gr. brn sdy L	fr					PS .3
		6-21	mod sab KC	fi sp					
		21-47	mfsab Rck	fi-sp 60					
		47-57	(BC) mdsb yKCl						
2	108A	0-12	gr brn SL	fr					PS .3
		12-43	sab KC yKCl	fi sp-sop					
		43-60	mdsb Rck	fi sp					
3	107A	0-9	gr brn L	fr					PS .3
		9-36	sab R c/cC	fi-fr sop					
		36-59	MSAB Rck	fi sp-pl sop					
			(Consolidated)	sp					
4	107A	0-4	gr brn SL	fr					PS .3
		4-38	mfsab Rck	fi					
		38-42	mdsb yR Rck	fi sp					
			fgr-cons	sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

MOORS END
COMMON OPEN SPACE
RESERVED FOR SEPTIC FIELDS
35' SETBACK
20' PSDE
143'
140'
130'
262'
sq. ft.
Pit
113
109
108
110
111
112
114
L=479.13'
R=125.00'
Delta=219°45'46"
R=210.00'
L=556.10'
Tan=833.69'
Delta=151°43'25"
R=235.00'
R=150.00'
S37°19'28"W
220.00'
S69°00'34"E
107.87'
S80°54'20"E
122.00'
344'
42'
58'
95'
252'
65'
71'
48'
116'
30'
24'