DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8-7-88
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 9 phase 1 B Thorpe PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	Sr brksl	fr					PS #3
		8-16	BLSCRB c-l-l	fr-firm w/ some plas for SCL/SCP					
			hard rock @ 36" on ridge with 3 pits						
2	#25 TEST	0-4	sr brksl	fr					PS #3
		4-28	BLSCRB cl	fr-firm					
		28-54	multicolored	fr-firm					
			brk SCP						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


SEPTIC FIELDS
ACRE
KINGSBURY COURT
213'
2+00
40'
R/W
22'
B=B
1+00
83'
10
51,629. sq. ft.
CRAWL
80 X 100
BASEMENT
50'-SETBACK
346'
DRIVE
9
48,375
sq. ft.
CRAWL
802
BASEMENT
243'
105'
119'
drive
103'
204.27'
=304.77'
Tan=188.78'
Delta=85°29'13"
PC = 0+47.57
105'
28+00
0+00
S83°32'59"E
860.49'
222'
R=44'
PT = 28+89.17
R=50'
8
CRAWL
70X90
7
41,697 sq. ft.
drive
120'
20' PSDE
L550
=335.00'
L=333.73'
Tan=182.19'
Delta=57°04'42"