4635196651

15517

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR MI Homes DATE April 26, '93 PERMIT NO. 26-23A-31

PHONE: Business _____ Home _____

LOCATION 1100 TR 1113 TR Waterford Drive At end on Right

S.R. No. _____

SUBDIVISION NAME Pine Isle LOT NO. 31 SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 4 No. Bathrooms 2½

Garbage Disposal Unit Yes ☑ No ☐

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 2 28,600 ft²

Soil Characteristics PS clay


Application Rate .3 gpd/ft²/day

Topography 2-6%

Depth to Water Table > 4'

Rock or other impervious formations None obs

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank ST 1500 / PT 1500 Gals.

Nitrification Field:

No. of Lines 4

Sq. Ft. _____ Linear Ft. 270 'of

Depth of Stone in Lines 16" ABPS

Water Supply: Individual ☐ Public ☑ pressure dosed

Installed by Osbison

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY DCK

COMMENTS Lowest Line shortest due to driveway cut (61 panels total)

System installed 2/24/93 - corrected maintenance agreement rec'd on 4/26/93 Operation permit

CERTIFICATE OF COMPLETION BY JR Hinson DATE 4/26/93

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold