DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Site bldg plot

OWNER: CRT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-6-8
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 98 The Pointe PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND: SCAPE POSITION/ SLOPE %	HORI: ZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR: HORIZ	PROFILE CLASS & LTAR
1		0-12	accompanying Soil pit						1S 125-3
		12-33	sl rb C	lt sp					
		33-48	mod C	lt sp					
			Layer of loamy fill						
2	TP #2 silt	0-6	plowed						P 3
		6-43	mod sb FC	lt sp some					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

20' PSDE
128'
125'
269'
150'
116'
249'
115'
191'
274'
L160
86
87
CRAWL
80²
BASEMENT
CRAWL
80²
BASEMENT
4@10'
pm MOD 25% RD
w/ MOD Repair
likely panel tilt
S57°11'28"E
119.73'
S32°48'28"E
110.00
14 +00
15 +00
13 +00