DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT:_____ OWNER:__AGENT:__ PHONE:_____
ADDRESS:_____ APPLICATION DATE:_____ DATE EVALUATED: 9/29/93
PROPOSED FACILITY: 4bedroom SF Dwelling
PROPERTY SIZE:_____
LOCATION OF SITE: Lot 60 Pine Dale
WATER SUPPLY: On-Site Well____Comm. Well__Public___Other_____EVAL. METHOD: Auger Boring ✓ Pit___Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	SS	0-11"	SAB / CL	1:1 / FR.	—	—	PS	—	.5
		11-22"	SAB / C	1:1 / Fi	—	—	PS	—	.35
		22-48"	wkSAB / SICL	1:1 / FR.	—	—	PS	—	.3
2									
3									
4									
5									

AVAILABLE SPACE (.1941): 4 SITE CLASSIFICATION (.1948): 4 SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: Hoffman, RS OTHER(S) PRESENT: Hans Baker
COMMENTS: House site appears to need changing (ie flip plan and move closer to lake w/ 1# PBPS original & repair area upslope & house.
Revised plan looks OK w/ driveway & garage entrance on left side.
Site will require PPBPS per rule of 1956