DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 2623A66
PROPERTY RECORDED: 45
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: MI Homes OWNER: AGENT: PHONE:
ADDRESS: 1043 E Morehead APPLICATION DATE: DATE EVALUATED: 9/17/93
Charlotte PROPOSED FACILITY: 4 bedroom SF Dwelling
PROPERTY SIZE: ~½ ac.
LOCATION OF SITE: Lot 66, Pine Isle (1100 TL 113, Th Waterford Rd Parkwood on (L ft)
WATER SUPPLY: On-Site Well Comm. Well ✓ Public Other EVAL. METHOD: Auger Boring ✓ Pit Cut

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	55	0-8"	gr/sbk/cl	1:1/fr	—	Some Scattered Small rock	PS	—	.4
		8-37"	sbk/c	1:1/fi	—	—	PS	—	.3
		37-41+	sbk/cl	1:1/fr	—	—	PS	—	.3
2									
3									
4									
5									

AVAILABLE SPACE (.1945): U SITE CLASSIFICATION (.1948): U SITE LONG-TERM ACCEPTANCE RATE: .3 gal/ft²/day
EVALUATED BY: [illegible] OTHER(S) PRESENT:
COMMENTS: Site can be reclassified PS per 1956 modified system PBPS