DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 2623A71
PROPERTY RECORDED: YES
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: MI Homes OWNER: AGENT: PHONE:
ADDRESS: 1043 E Morehead Charlotte APPLICATION DATE: 10/12 DATE EVALUATED: 10/13/83
PROPOSED FACILITY: 3 Bedroom SF Dwelling
PROPERTY SIZE:
LOCATION OF SITE: Lot 71, Pine Dale, corner of Tripridge (Rusty) and Rockrimmon
WATER SUPPLY: On-Site Well ___ Comm. Well ___ Public ✓ Other ___ EVAL. METHOD: Auger Borings ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	SS	0-6"	SAB / SCL	1:1 / fi (Dev)	—	—	PS	—	.5
		6-24"	SAB / C	1:1 / vfi (Dev)	—	—	PS	—	.35
		24-48	wk SAB / SICL	1:1 / fr	—	—	PS	—	.3
2									
3									
4									
5									

AVAILABLE SPACE (.1949): PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: [illegible] OTHER(S) PRESENT:
COMMENTS: Only one of a few lots in this subdivision that can accomodate a conventional system.