4635 36 7122

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donna Donatelli DATE 10/31/79 PERMIT NO. 379

PHONE: Business _____ Home _____

LOCATION 1100 TL on 1113 3rd House on Rt after entering Isle of Pines S. R. No. _____

SUBDIVISION NAME Isle of Pines LOT NO. 26 SECTION OR BLOCK NO. 1


House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 4 No. Bathrooms 3

Garbage Disposal Unit	Yes	(✓)	No	( )	
Auto. Dishwasher	Yes	(✓)	No	( )	
Auto. Wash. Machine	Yes	(✓)	No	( )	
Site Suitable	Yes	(✓)	No	( )	

Lot Area ~1/2 AC

Character & Porosity of Soil Clay loam
Percolation Rate 30 mpi
Topography 2-4%
Depth to Water Table 4'+
Rock or other impervious formations none obs.



Plot of System

Size of Tank Existing Gals.
Nitrification Field:
No. of Lines 1
Sq. Ft. 462 Linear Ft. 154
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Wayne Robinson

IMPROVEMENTS PERMIT BY _____

COMMENTS: Repair starts 3' wide and tapers into 6' wide

CERTIFICATE OF COMPLETION BY Harold R. Johnson DATE 10/31/79

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donna Donatelli DATE 10/31/79 PERMIT NO. 379

PHONE: Business _____ Home _____

LOCATION 1100 Tk on 1113 3rd House on Rt after entering Isle of Pines S. R. No. _____


SUBDIVISION NAME Isle of Pines LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 4 No. Bathrooms 3

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	Clay loam
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	30 mpi
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
			Rock or other impervious formations	none obs.

Lot Area ~1/2 AC



Plot of System

Size of Tank Existing Gals.
Nitrification Field: 1
No. of Lines
Sq. Ft. 462 Linear Ft. 154
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Wayne Robinson

The proposed / existing GARAGE addition does not appear to impact the existing septic system.
**NOTE: _____

REHS R.S.
Date: 12-3-09
ICHD-Environmental Health Division

IMPROVEMENTS PERMIT BY _____

COMMENTS: Repair starts 3' wide and tapers into 6' wide

CERTIFICATE OF COMPLETION BY Harold R. Johnson DATE 10/31/79

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold