DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Fox APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4/16/99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lake Hills Estates Lot # 8 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Lot #9 AA-2 - over

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	A++	0-14	Brw SL GR FR						
		14-32"	Brw to Rd/Brw CL	m-wSBK SS SP, SE, FR					PS .25 to .3
		32-48"	Rd/Brw CL	wSBK S-SS, SP SE	FRw/low chroma				
				Relic mottles					
		X	Remove old berms						
2	A++2	0-2	Brw SL GR FR						
		2-45	Brw CL/CL	m-wSBK S-SS, SP SE	FI-FR				PS .25-.3
		45-48	Rd/Brw CL	m-wSBK SS, SP SE	FR				
3	Pit 5/12/03	0-10	Brw SL	GR FR					
		10-26	Rd/Brw CL/CL	m-wSBK SS, SP, SE	FI-FR				PS .3
		26-48	Rd/Brw CL	wSBK SS, SP, SE	FR w/ Ye/Brw to 48"				
			Common mica flakes & few						
			SAP	Inclus					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____