4635 49 6226

IREDELL COUNTY HEALTH DEPARTMENT

13366 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Leonard Cremen DATE 11/27/91 PERMIT NO. 26-8-A-22

PHONE: Business _____ Home _____

LOCATION Marina Village - Southwood Drive - 1100 TR on Stutts, TR on Southwood (1st) TL to 4th lot on (R)

S. R. No. _____

SUBDIVISION NAME Marina Village LOT NO. 22 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil P-C (sf)
Percolation Rate P .35
Topography P - 2-3%
Depth to Water Table >48"
Rock or other impervious formations None found

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Size of Tank 1000 Septic Tank 1000 Pump Tank Gals.

Nitrification Field:
No. of Lines 5
Sq. Ft. _____ Linear Ft. 180
Depth of Stone in Lines 12" SAND

Water Supply: Individual (✓)
Public ( )

Installed by AH Stewart

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

+ Operations Permit

IMPROVEMENTS PERMIT BY _____

COMMENTS: 11/27/91 - Drainfield passed. 2/12/92 - Pressure head adjusted to 2 foot, alarm functioned and installed in utility room.

CERTIFICATE OF COMPLETION BY Wesley Sparks RS DATE 2/12/92

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold