IREDELL COUNTY HEALTH DEPARTMENT 4635-57-7836

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert P Hensel DATE 5-31-83 PERMIT NO. 176

PHONE: Business _____ Home _____

LOCATION 1100 TL 1112 AT END TR 5th Lot on left

S. R. No. _____

SUBDIVISION NAME Imperial Point LOT NO. 31 SECTION OR BLOCK NO. _____

House (X) Mobile Home ( ) Business ( ) Other _____ Adding Car port


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (X)
Auto. Dishwasher	Yes (X)	No ( )
Auto. Wash. Machine	Yes (X)	No ( )
Site Suitable	Yes (X)	No ( )

Character & Porosity of Soil _____
Percolation Rate _____
Topography Existing System
Depth to Water Table _____
Rock or other impervious formations _____

Lot Area Existing

(X) Basement with Plumbing Car Port ( ) Basement without Plumbing ( ) No Basement



Existing System
Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 715 Linear Ft. 260
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public ( )

5-24-73
Installed by J. Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

System installed for Barbara Hildeford

Signed: _____

System installed 5-24-73 checked by J.C. Moore

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing system working ok at time of Inspection

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: Fred Clemmer DATE 5-31-83

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold