DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 23176
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Sidney Blankenship APPLICANT: Same
ADDRESS: 91 Crescent Place Ln. APPLICATION DATE: 2/ DATE EVALUATED: 2/26/96
PROPOSED FACILITY: 3BR Res. PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 163 x 160 x 135
LOCATION OF SITE: Brawley school - TL Stutts - T R Bay watch - TL South wood PROPERTY RECORDED: ___
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	2%	0-6	SCL WGR	FRI					PS .35 gpd/ft²
		6-12	C SBK	FI					
		12-48	CL WSBK	FRI					
2	2%	0-4	SCL GR	FRI					PS .35 gpd/ft²
		4-8	C SBK	FI					
		8-48	CL WSBK	FRI					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1018	
System Type(s)	Conventional	Panel
Site LTAR	.35 gpd/ft²	.35 gpd/ft²

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Brady Freeman
OTHER(S) PRESENT: Sidney Blankenship