4635-69-5673

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Sam McNinch DATE Jan. 29, 80 PERMIT NO. 12

PHONE: Business _____ Home _____

LOCATION 1100 ft on 1112 ft on 2nd entrance to Commodore Dr. ~1/2 mi. on left S. R. No. _____


SUBDIVISION NAME Commodore Peninsula LOT NO. 161 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay loam	
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	80 mpi	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	sunk.	
			Rock or other impervious formations	none obs.	

Lot Area ~1/3 Ac.



Plot of System

Size of Tank Existing Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 10"

Water Supply: Individual ( )
Public (✓) Community Well

Installed by H. J. Erwin

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Repair deep.

CERTIFICATE OF COMPLETION BY Mark R. Henson DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold