Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 OF 1
PIN #: 4635-86-6277
Lot #: 6
Permit #: 176922
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: **TINA OUELLETTE**
Applicant: **SAME**
Address: **338 CAMINO REAL RD.**
Date Evaluated: **3/8/2013**
Proposed Facility: **REPAIR** Design Flow (.1949)
Property Size:
Location of Site: **LAKEVIEW PARK LOT 6**
Property Recorded: **YES**
Water Supply: [ ] Public [X] Individual [X] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY 1941 .1941 Structure/ Texture	SOIL MORPHOLOGY 1941 1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	1956 Sapro Class	1944 Restr Horiz	Profile Class & LTAR
AB 1	LINEAR 3%	0-36	BRSCL,W,SBK	SS,VFR	FEW YELLOW MOTTLES	48"	NA	48+	.25
		36-48	RC,M,SBK	S,FIRM					
AB 2	LINEAR 3%	0-36	BRSCL,W,SBK	SS,VFR	FEW YELLOW MOTTLES	48"	NA	48+	.25
		36-48	RC,M,SBK	S,FIRM					

Description	Initial System	Repair System
Available Space (.1945)		PS
System Type(s)		G-25%
Site LTAR		.25

Other Factors (.1946):
Soil Evaluation By: **BEN ALDRIDGE**
Others Present: **NONE**
Site Classification (.1948): **PS**
Site Evaluation By: **BEN ALDRIDGE**
Others Present: **BRADY FREEMAN**