DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jim Faulkner / Cassidy
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: Residential PROPOSED DESIGN FLOW (.1949): 360 DATE EVALUATED: _____
LOCATION OF SITE: Camino road Guest House PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☒ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
Guest house 1	Back of 2nd line- next to old system	0-8	1sbk cl			48			PS .25 angular structure in landscape position
		8-48	1sbk/1abk cl	fr ss/sps e					
6ft 2	Front of GH	0-6	1sbk sl			48+			PS .3
		6-33	1sbk cl	fr					
		33-48+	1sbk/1abk c	fr ss/sps e					
3	in gravel road front	0-10	1sbk cl	fi	Remowe 10"				.25
		10-38	1sbk cl	fr ss/sps e					
		38-48	1sbk/1abk c	fr					
4		0-6	1sbk cl			48			.25-.3
		6-48	1sbk/1abk cl	fr ss/sps e					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)	LP Panel	LP Panel
Site LTAR	.25	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: J Melville
OTHER(S) PRESENT: _____

COMMENTS: includes area under gravel road