DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tappan Real Estate Investors
ADDRESS: 435 Sixth Avenue Pittsburgh PA 152190000
PROPOSED FACILITY: 8 Bdrm
PROPOSED DESIGN FLOW (.1949): 960 gpd
LOCATION OF SITE: 238 Camino Real
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

APPLICATION DATE 3/08
DATE EVALUATED: 1/08
PROPERTY SIZE:
PROPERTY RECORDED:

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L/6-10	0-10	BR C l fsbk	Frsssps: -r	-f organics	52	-	-	PS 0.3
		10-52	RBC mfsbk/abk	" " "					
2	L/6-10	0-8	BR cl fsbk	Frsssps: -r	-f orgn. cs	52	-	-	PS 0.3
		8-52	RBC mfsbk/abk	" " "					
3	L/6-10	0-10	BR cl fsbk	Frsssp5exp	-f organics	52	-	-	PS 0.
		10-52	RB cmfsbk/abk	" " "					
4	L/6-10	0-12	B cl wsbk/gr	Frsss p5 exp		52	-	-	PS 0.3
		12-52	RC mfsbk/abk	" " "					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

COMMENTS:

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tappen Real Estate Investors — APPLICATION DATE 3/08
ADDRESS: 1435 Sixth Avenue Pittsburgh PA 152190006 — DATE EVALUATED: 1/08
PROPOSED FACILITY: 8 Bdrm — PROPOSED DESIGN FLOW (.1949): 960 gpd — PROPERTY SIZE:
LOCATION OF SITE: 238 Camino Real — PROPERTY RECORDED:
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut — TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L/6-10	0-10	BR C 1 fsbk	Frsss psexp	-f organics	52	-	-	PS 0.3
		10-52	RBC mfsbk/Abk	" " " "					
2	L/6-10	0-8	BR cl fsbk	Frsss psexp	-f organics	52	-	-	PS 0.3
		8-52	RBC mfsbk/Abk	" " " "					
3	L/6-10	0-10	BR cl fsbk	Frsss psexp	-f organics	52	-	-	PS 0.3
		10-52	RB cm fsbk/Abk	" " "					
4	L/6-10	0-12	B cl wsbk/sg	Frsss PSEXP	-	52	-	-	PS 0.3
		12-52	RC mfsbk/Abk	" " "					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

COMMENTS: