SOIL SITE EVALUATION
(Continuation Sheet)

Sheet of

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

PROPERTY ID NO.: Ches. Pt. Lot
DATE OF EVALUATION: 3-2-86
COUNTY:

Lot 31 & 30

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON ON DEPTH (IN.)	SOIL MORPHOLOGY .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
Lot 31 1	(33) 5-7%	0-12	wsbk sl	SS SP Fr	Br				50" .3
		12-38	msbk C	SS SP Fr	R				
		38-50	wsbk sl	SS SP Fr	R C Sap				
2	6-8%	0-16	wgr sl	SS SP Fr	Br				55" .3
		16-35	msbk C	SS SP Fr	R FSap				
		35-55	wsbk cl/sl	SS SP Fr	R				
Lot 30 1	(32) 5-7%	0-12	mgr sl	SS SP Fr	Br				50" .3
		12-30	msbk C	SS SP Fr	R FSap				
2	6-8%	0-20	msbk C	SS SP Fr	R				50" .3
		20-52	wsbk sl	SS SP Fr	R C Sap				

COMMENTS:

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 7/26/06
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 30 (New #13) PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1									
2									
3	L 6-7%	0-5	mgr sl	FR SS/SP	Bt				PS 0.3
		5-27	msbk c	F SS/SP	K				
		27-49	wsbk scl	FI SS/SP	K FJC sap mottles				
			Opposite wall Sap(SI) starts @ 30"						
4	9-26-06 10% V	0-5	g-wksbk sl/scl fr ss sp						.3
		5-17	m-fsbk mod c-fr ss sp						
		17-52	wksbk cl-sap fi-fr ss sp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Martin & Jacobs
OTHER(S) PRESENT: _____

COMMENTS: _____

50' VEGETATIVE BUFFER
LOT 31
1.10 ACRES
S48°13'32"E 526.49'
LOT 30
1.24 ACRES
S48°13'32"E 553.67'
LOT 29
1.29 ACRES
S48°13'32"E 565.9
449.59'
170'
65'
20'
145'
Drive
35' MBSL
COVE CREEK ROAD
10' D & U

LOT 30