Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet:
Property ID: 4636-05-5671
Lot #: 8
File #: Repair
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Herman Kruger
Applicant:
Address:
Date Evaluated:
Proposed Facility: Design Flow (.1949) 240 GPD
Property Size:
Location of Site: Lopez Mobile Home Park Lot 8
Property Recorded: Yes
Water Supply: [ ] Public [x] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [x] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB 1	<2%	0-12	SCL,M,SBK	SS,SP,SEXP,VFR	NA				
	LINEAR	12-48	C/CL,M,SBK	SS,SP,SEXP,FR	NA	48"	NA	NA	.3

Description	Initial System	Repair System
Available Space (.1945)		PS
System Type(s)		25%
Site LTAR		.3

Other Factors (.1946):
Soil Evaluation By: Ben Aldridge
Others Present: None
Site Classification (.1948): PS
Site Evaluation By: Ben Aldridge
Others Present: Herman Kruger