DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 3-22-05
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 1 Beechtree Bay PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5-10% L Now part of SFE 1A	0-26	gr brn sl/sl	fr ss p					0.3
		26-45	brnish RC	fr sp-ss sp sep					
		45-54	mottled LSAP	fr ss sp	few mn lo				
2	part of SFE 1A 6-7% L	0-10	wk sbk brn sl/sl	fr ss p					.25:3
		10-34	mottled R tight C	fr ss sp sep					
		34-57	wk sbk gry cl	fr ss p	few mn gravel coatings				
3	This pit Now in Revised Street Location	0-21	wk sbk brn cl	fr ss p					.20 L 36"
		21-36	wk sbk brn c	fr s sp sep	few mn gravel coatings				
		36-60	wk sbk rd/sl	fr ss p	common yellow brn mottles; common mn gravel coatings; few cl 3/4 mottles water bleeding out of soil at 58"				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___