DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Cheasapeake Rl. APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 7-14-06
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 38 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
3A 1	L 2-4%	0-26	msbk c	FR SS/SP	R F; WR				.25-.3
		26-48	MA SP	FR SS/SP	R C; WR & SAP				
		Pit beside is WS to Rock		dne	NW corner pit has WR starting @ 13"				
2	L 4-6%	0-21	mgr sl	FR SS/SP	H. br				.3
		21-42	msbk c	F/FR SS/SP	R				
		42-49	msbk cl	FR SS/SP	R Few sap inclu.				
4 3B	8-24-06 5% S	0-6	gr sl	FR SS/SP					.3
		6-19	msbk mod c	FR SS/SP SAP	Few in SAP				
		19-52	msbk mod cl	FR SS/SP					
4	get soil notes on pit (3) Crack SEE LOG Lot 36					@38"			.3-.25

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____