DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: _____
LOCATION OF SITE: lot 9 Stonegate PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	BSCL GR	fri sssp					.2
		4-60	YB/RBC/CL APK	fi; sp	YB's/mang. stains				
2		0-24	RC SLM	fi sp					.25
		24-64	RB/YBCL mtxd	fr sssp/sp	common YB's				
3		0-3	BSCL GR	fri sssv					.2 to 30"
		3-30	RC APK	fi sp	common YB's				
		30-98	RYC AOM	fi sp	2 chroms @ 30"				
4		0-3	gr trnsct	fr sssp					.25
		3-32	WK fSBK	RSC fr SP SEXP					
		32-43	WC AB/SB	YR-RY CL fi sssp	reduced colors				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

(3) 0-4 gr trnsct fr sssp
4-24 WK fSBK RSC fr SP SEXP .25 @ ~ 30" ~ 184/6 or .1-.125 LTAR
24-30 WK AB/SBK YR-RY CL fi sssp common manganese stains
@ 30" few chr 2