DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 11 Stone gate PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	BSL GR	fri SSSP					PS 13
		4-21	RL SBK	fi SP					
		21-56	RL MASSIVE	fri SSSP - common SAP @ 40"					
		56-60	SL SAP	fri MSMP					
2		0-6	BSL GR	fri SSSP	31"+				.2-.25 @ 19"+6
		6-45	SBK YR SC with SAP	FRSP SEPT mottled					
3		0-4	gr brn scl	fr SSSP	common mod SAP				.3
		4-16	SBK RC	fr SSSP					
		16-30	MASBK RCL	fr SSSP					
		30-44	WK SBK SL SAP	fr SSSP					
4	stay above this	0-5	gr brn scl	fr SSSP					.2-.25
		5-15	WK SBK R-Y-yBRN CL	fr SSSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

AK (5) 0-3 gr brn scl fr SSSP
3-27 SBK yR C fr SP
27-33 WK SBK gy brn CL fr SSSP .25 @ 18"+6
dm 2@30"+