DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 10-9-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 107 Stonegate PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-60	RRC SaL fi	SP /	WBs				.2
2		0-24	VR C/SL WSBK fi	SP+	2 chroma @ 33"+ Inc of expansive @ 33"+				.2
3	10-14-02	0-3	gr sandy L	fr SSP					(1)
		3-22	WSBK RCL	fr SSP	22"+				
		22-66	MK SAL/MB yr SCL/L	fi SSP	many chr 2 drainage matrix				
4		0-7	gr brn SL	fr SSP					.3
		7-28	SBK RC	fr SP/SSP					
		28-48	wk SBK RCL	fr SSP	common inf sapr				
		48-57	massive LS/SL	fr SSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

#5 0-6 gr brn sL
6-30 SBK c fr sp 32"+ chr 2
30-58 MB yr & fi sp .25 @ <30" either LP or Shallow Bed