DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 10-3-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 6 Stones St PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☑ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-7	gr bnr scl	fr sso					.1-.125 LPT
		7-24	wf sbk R c/d	fi fr sso					
		24-53	massive Rey scl	fi sso	common glauc 32-53"	faint redmgo			
		53-64	Massive Gy LSap	fi sso		quartz rock mp			
			& Relict						
2		0-7	gr wk sbk brn scl	fr sso					.1-.2
		7-17	wk sbk R c/d	fr sso	few manganese coatings/concretions				
		17-64	Massive-wk sbk R brn scl	fi sso-sp	common gl brn				
					few ch zk	common manganese			
					distinct lateral water movement				
3		0-5	gr wk sbk brn scl	fr sso					.1-.2
		5-18	wk sbk R c/d	fr sso-sp	common manganese coatings				
		18-60	wk sbk brn scl	fi sp	few common glauc sand				
					distinct lateral water movement				
4		0-5	gr wk scl	fr sso-sp					.3
		5-36	sbk RC	fr sso-sp					
		36-53	wk sbk mass	fr sso-sp	common mi sap				
		53-70	LSap	fr sso-sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____